

When Releasing Steelwork, Fabricator must be sure that the Steelwork is free of ALL paint/metal marking. See below arrows indicating that this was not done when the steelwork was sent for Galvanizing!

